


## Installing CDR HS USB Remote

1. Browse to the Server
2. Open "Techworksinc" Share
3. Open "Software" folder
4. Open "ES v17 RC3 Digital Integration" folder
  - a. Path: \\[SERVER]\Techworksinc\Software\ES v17 RC3 Digital Integration
5. Double-click "digital.exe"
  - a. This will open an installer in order to choose the sensor option to install
6. Click "I/O – Panoramic" underneath "Schick by Sirona"



7. Verify the remote box is unplugged from the machine
8. Click "OK"




9. Click Next



10. Check the box that says CDR HS USB

11. Click Next



12. Click Install

